



C.L. "BUTCH" OTTER – Governor
RICHARD M. ARMSTRONG – Director

IDAHO DEPARTMENT OF HEALTH & WELFARE

DEBBY RANSOM, R.N., R.H.I.T – Chief
BUREAU OF FACILITY STANDARDS
3232 Elder Street
P.O. Box 83720
Boise, Idaho 83720-0009
PHONE: (208) 334-6626
FAX: (208) 364-1888
E-mail: fsb@dhw.idaho.gov

September 16, 2010

Thair Pond, Administrator
Tomorrow's Hope-- Armga
1655 Fairview Avenue, Suite 100
Boise, Idaho 83702

RE: Tomorrow's Hope - Armga, Provider #13G014

Dear Mr. Pond:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Tomorrow's Hope-- Armga, on September 8, 2010.

Enclosed is your copy of a Statement of Deficiencies/Plan of Correction, form CMS-2567, which states that no Medicaid deficiencies were noted at the time of the survey. Also, enclosed is a similar form stating that no State licensure deficiencies were noted at the time of the survey.

Thank you for the courtesies extended to us during our visit. If we can be of any help to you, please call our office at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY
Health Facility Surveyor
Facility Fire Safety and Construction Program

TB/lj

Enclosure

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 09/14/2010
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 13G014	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING _____		(X3) DATE SURVEY COMPLETED 09/08/2010
NAME OF PROVIDER OR SUPPLIER TOMORROW'S HOPE - ARMGA			STREET ADDRESS, CITY, STATE, ZIP CODE 12306 WEST ARMGA MERIDIAN, ID 83642		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
K 000	<p>INITIAL COMMENTS</p> <p>The facility is a single story, type V (000) building built in 1981. The facility is protected by a 13 D automatic fire sprinkler system with quick response heads in habitable spaces. There is a complete fire alarm/smoke detection system installed. Currently the building is licensed for 7 ICF-MR beds. The survey was conducted in accordance with 42 CFR 483.470.</p> <p>The facility was found to be in substantial compliance with applicable fire/life safety requirements set forth in the Life Safety Code, 2000 edition, Chapter 33, Existing Residential Board and Care Occupancy, Impractical Evacuation Capability. The survey was conducted on September 8, 2010, in accordance with 42 CFR 483.470.</p> <p>The annual life safety code survey was conducted by:</p> <p>Taylor Barkley Health Facility Surveyor Facility Fire Safety & Construction Program</p>	K 000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 13G014	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING _____	(X3) DATE SURVEY COMPLETED 09/08/2010
NAME OF PROVIDER OR SUPPLIER TOMORROW'S HOPE - ARMGA		STREET ADDRESS, CITY, STATE, ZIP CODE 12306 WEST ARMGA MERIDIAN, ID 83642		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
M 000	<p>16.03.11 Initial Comments</p> <p>The facility is a single story, type V (000) building built in 1981. The facility is protected by a 13 D automatic fire sprinkler system with quick response heads in habitable spaces. There is a complete fire alarm/smoke detection system installed. Currently the building is licensed for 7 ICF-MR beds.</p> <p>The facility was found to be in substantial compliance with applicable fire/life safety requirements set forth in the Life Safety Code, 2000 edition, Chapter 33, Existing Residential Board and Care Occupancy, Impractical Evacuation Capability. The survey was conducted on September 8, 2010, in accordance with IDAPA 16.03.11 Rules Governing Intermediate Care Facilities for the Mentally Retarded (ICF-MR).</p> <p>The annual life safety code survey was conducted by:</p> <p>Taylor Barkley Health Facility Surveyor Facility Fire Safety & Construction Program</p>	M 000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE